

Oil Field Environmental Incident Summary

Incident: 20160509143652 **Date/Time of Notice:** 05/09/2016 14:36

Responsible Party: OASIS PETROLEUM NORTH AMERICA LLC

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: SANDAKER 5602 11-13H

Field Name: TYRONE

Well File #: 18418

Date Incident: 5/8/2016

Time Incident: 16:00

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 102

Sec: 13

Qtr: NW NW

Location Description:

Submitted By: Luke Radke

Received By:

Contact Person: Luke Radke
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	40	Barrels	40	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Take treater out of service and replace all gaskets

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 5/9/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained. More follow-up is needed.

Date: 5/11/2016 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

5/11/2016 at 10:37, on location. It appears that a spray of oil came out of the heater treater located in the northcentral portion of the wellpad. The spray blew north/northwest onto both sides of the county road bordering the north side of the wellpad, as well as into an untilled field on the north side of the county road, across from the wellpad. The vegetation in the field has been cut, but vegetation on either side of the county road shows signs of staining. Pipeline markers in the area also show staining. More follow-up required.

Date: 11/3/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 1:56, 11/3/2016.

No sign of impacts at the time of inspection. Contact responsible party to see if samples were taken.

More follow-up is necessary.